



Ready

NUM

File View Edit Tools Window Help

Drafts Pending Active L1: (49) 219/\$7.ccls. and (weld\$3 with foam)
L4: (3096) (weld\$3 with foam)
L5: (3047) 4 not 1
ocr L6: (8) 219/\$7.ccls. and (weld\$3 with foam)
L7: (83) 5 and (nozzle with foam)
L8: (12) fujikura.asn. and (weld\$3) and foam
L9: (2964) 5 not 7
ocr L10: (208) (weld\$3 with foam)
ocr L11: (11) 10 and (nozzle with foam)
ocr L12: (197) 110 not 11
ocr L15: (31) 12 and foam.ti.
ocr L16: (31) 15 and weld\$3
ocr L17: (166) 12 not 16
L23: (87) 9 and (weld\$3.ti. near2 foam.ti.)
L24: (8) (welding adj head) with foam
L25: (13) (welding near3 head) with foam

Failed Saved Favorites Tagged (0) UDC Queue Trash

Search Browse Queue Clear DBs USPAT; US-PGPUB; EPO; JPO; DERWE; Plurals Default operator: OR Highlight all hit terms initially

(welding near3 head) with foam

BR5 term IS&R form Image Text HTML

Ready NUM

East general search
10/792, 196
8-405

[New] [Open] [Save] [Print] [Help] [Exit]

- Drafts
- Pending
- Active
 - L28: (30) welding.clm. near4 foam.clm.
 - L29: (74) butt near3 foam
 - L36: (3) (nozzle near3 foam) with welding
 - L37: (9) (nozzle with foam) with welding
 - L38: (6) 37 not 36
- Failed
- Saved
- Favorites
- Tagged (0)
- UDC
- Queue
- Trash

Search List Browse Queue Clear

DBs USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

Default operator: OR

Plurals

Highlight all hit terms initially

37 not 36

BRS form IS&R form Image Text HTML

No Details HTML

File View Edit Tools Window Help

Drafts Pending Active L28: (30) welding.clm. near4 foam.clm.
L29: (74) butt near3 foam
L36: (3) (nozzle near3 foam) with welding
L37: (9) (nozzle with foam) with welding
L38: (6) 37 not 36 Failed Saved Favorites Tagged (0) UDC Queue Trash

Search List Browse Queue Clear

DBs USPAT US-PGPUB EPO JPO DERWENT IBM_TDB Plurals Highlight all hit terms initially

Default operator: OR

37 not 36

BRS form SAR form Image Text HTML

Details BRS HTML

Ready NUM

File View Edit Tools Window Help

Drafts Pending Active L1: (207) 156/\$7.ccls. and (weld\$3 with foam)
L7: (29) 156/\$7.ccls. and (weld\$3 with carpet)
L9: (29) 7 not 1
L11: (20) 156/\$7.ccls. and (butt near8 foam)
L12: (7) 11 not (1 or 7)
L13: (11) 156/\$7.ccls. and (butt near8 carpet)
L14: (7) 13 not (1 or 7 or 12)
ocr L15: (48) 156/\$7.ccls. and (weld\$3 with foam)
ocr L16: (3) 156/\$7.ccls. and (weld\$3 with carpet)
ocr L17: (51) 15 or 16
ocr L18: (46) (weld\$3 with (foam or carpet)) and (handle)
L19: (240) (weld\$3 with (foam or carpet)) and (handle)
ocr L20: (41) 18 not (15 or 16 or 17)
L21: (206) 19 not (1 or 7 or 9 or 11 or 12 or 13 or 14)
L22: (349) (butt adj welding) and handle
L24: (0) 23 and 156/\$7.ccls.
L23: (206) 21 not (1 or 7 or 9 or 11 or 12 or 13 or 14)

Failed Saved Favorites Tagged (0) UDC Queue Trash

Search Last Browse Queue Clear DBs USPAT US-PGPUB EPO JPO DERWENT IB Plurals Default operator OR Highlight all hit terms initially

21 not (1 or 7 or 9 or 11 or 12 or 13 or 14)

BRS form ISRF form Image Text HTML

Ready NUM

East general search
8-4-04

File View Edit Tools Window Help

Drafts Pending Active L1: (207) 156/\$7.ccls. and (weld\$3 with foam)
L7: (29) 156/\$7 ccls. and (weld\$3 with carpet)
L9: (29) 7 not 1
L11: (20) 156/\$7.ccls. and (butt near8 foam)
L12: (7) 11 not (1 or 7)
L13: (11) 156/\$7.ccls. and (butt near8 carpet)
L14: (7) 13 not (1 or 7 or 12)
ocr L15: (48) 156/\$7.ccls. and (weld\$3 with foam)
ocr L16: (3) 156/\$7.ccls. and (weld\$3 with carpet)
ocr L17: (51) 15 or 16
ocr L18: (46) (weld\$3 with (foam or carpet)) and (handle)
L19: (240) (weld\$3 with (foam or carpet)) and (handle)
ocr L20: (41) 18 not (15 or 16 or 17)
L21: (206) 19 not (1 or 7 or 9 or 11 or 12 or 13 or 14)

Failed Saved Favorites Tagged (0) UDC Queue Trash

Searches list Browse Queue Clear
DBs USPAT US-PGPUB Plurals
Default operator OR Highlight all hit terms initially
19 not (1 or 7 or 9 or 11 or 12 or 13 or 14)

BRS form ISR form Image Text HTML

Ready NUM

File View Edit Tools Window Help

Drafts Pending Active L1: (207) 156/\$7.ccls. and (weld\$3 with foam)
L7: (29) 156/\$7.ccls. and (weld\$3 with carpet)
L9: (29) 7 not 1
L11: (20) 156/\$7.ccls. and (butt near8 foam)
L12: (7) 11 not (1 or 7)
L13: (11) 156/\$7.ccls. and (butt near8 carpet)
L14: (7) 13 not (1 or 7 or 12)
ocr L15: (48) 156/\$7.ccls. and (weld\$3 with foam)
ocr L16: (3) 156/\$7.ccls. and (weld\$3 with carpet)
ocr L17: (51) 15 or 16

Failed Saved Favorites Tagged (0) UDC Queue Trash

Search Last Browse Queue Clear DBs USOCR Default operator: OR Plurals Highlight all hit terms initially

15 or 16

BRS form I&R form Image Text HTML

Ready NUM

File View Edit Tools Window Help

Drafts Pending Active L5: (361) (weld\$3 with foam) with (edge\$1 or butt)
L6: (39) 5 and 156/\$7.ccls.
L8: (322) 5 not 6
L9: (12) 8 and travels
L10: (310) 8 not 9
L11: (22) 10 and handle
L12: (288) 10 not 11
L13: (43) 12 and gas
L14: (245) 12 not 13
L15: (9) 14 and trimming
L16: (236) 14 not 15
L17: (4) 16 and (interface with foam)
L18: (232) 16 not 17
L19: (3) 18 and nozzle
L20: (229) 18 not 19

Failed Saved Favorites Tagged (0) UDC Queue Trash

Search DBs USPAT:US-PGPUB: EPO:JPO: DERWENT: IBM_TDB Plurals Default operator: OR Highlight all hit terms initially

18 not 19

BRS form I&R form Image Text HTML

Ready NUM

